

**PIN 14     Engine Systems (MAS) control module - r129 300sl, w124 300e, w201 190e 2.6**

- 1 No fault
- 2 fuel pump relay not functioning
- 3 TD signal interrupted
- 4 Output for O2 sensor heater control defective
- 5 Output for air injection pump control defective
- 6 Output for kickdown switch control defective
- 7 Not used
- 8 Engine coolant temperature sensor signal out of range
- 9 Circuit 50 failure
- 10 Output failure of the start valve
- 11 A/C compressor engagement signal missing
- 12 Output for A/C compressor control defective
- 13 A/C compressor slippage too great
- 14 Speed signal implausible
- 15 Short circuit detected in fuel pump circuit