J2 AR09.10-P-1050GA


Removing and installing air cleaner

21.4.98


ENGINE 111.943/944/947/973/975

Model 170 with engine 111.943/973

Arrow Connector at actuator




Model 202, 208 with engine 111.944/975



P09.10-0214-06

Model 210 with engine 111.947

Arrow Connector at actuator



P09.10-0300-06

| Fig. item, etc. | Work instructions | | |
|-----------------|-----------------------|---|--|
| i | Connector at actuator | First of all raise catch at connector housing | |
| | | to unplug the connector | |

AR09.10-P-1050GA

| [i] | Pins of air cleaner | Press into rubber bush | |
|-----|---------------------|--|--|
| i | , | Model 170, 202, 208, 210 Retrofitting not possible, fit filter felt or | |
| | | foam to air cleaner element | |