


L4 AR09.20-P-5301G **Removing and installing partial intake manifold preheater**
3.8.94

ENGINES 111.940 up to 1.7.93,
111.960 up to 1.8.93
in **MODEL 124**

13/2 O-ring

 R8/2 Partial intake manifold preheater
(PMP)


P09.20-0236-04

Fig. item, etc.	Work instructions		
R8/2	Partial intake manifold preheater (PMP)	Do not exert any force on the contact pin or on the plastic part	
13/2	O-ring	replace. Oil for installing	