


83–602 Preparations for testing, connecting adaptor to Volt/Ohm measuring instrument

Preparations for test

- 1 Remove cover at the right under instrument panel (68–150).
- 2 Remove glove box (68–140).

Connecting adaptor to Volt/Ohm measuring instrument

- 3 Pull 12-point plug from electronic switchgear (9) for temperature control and connect to adaptor.



- 4 Connect adaptor with Volt/Ohm measuring instrument to 12-point plug and switch adaptor to test step 1.

